



Example: Cylindrical Contact Stress

$$E = 30 \text{ M}_\text{psi} \\ \nu = 0.292$$



$$b = \sqrt{\frac{2(1000b)}{\pi(0.5 \text{ in})}} \frac{(1 - 0.292^2)/30E \text{ psi} + (1 - 0.292^2)/30E_6}{\frac{1}{0.25''} - \frac{1}{2''}}$$

$$b = \frac{0.805}{0.00471''}$$

principal stresses @ z=0

$$P_{\max} = \frac{2(1000 \text{ lb})}{\pi b l} = 849 \text{ ksi}$$

$$\sigma_x|_{z=0} = \sigma_1 = -2VP_{\max} = -496 \text{ ksi}$$

$$\sigma_y|_{z=0} = -P_{\max} = -849 \text{ ksi}$$

$$\sigma_z = \sigma_2 = \frac{-P_{\max}}{\sqrt{1 + \frac{z^2}{l^2}}} = -849 \text{ ksi}$$

$$\epsilon_{\max}|_{z=0} = \frac{\sigma_1 - \sigma_3}{2} = 176.6 \text{ ksi}$$

Deformation and Stiffness

Chapter 4

Designs for high rigidity

- minimize misalignment
- avoid interference w/ other components
- reduce noise
- reduce wear rates
- reduce stress

Designs for high flexibility

- energy storage and absorption
- springs
- elastic deformation for change in dimensions
- snap rings



Rigidity deflection per load

- Mod. of Elasticity is good indicator of rigidity
- geometry of component is essential to characterize rigidity
- inverse of "spring constant" or "stiffness"

$$F = Kx$$

$$K = \frac{F}{x}$$

$$\frac{x}{F} \Rightarrow R$$