

## Crack Growth

### Stage I Crack initiation

- geometric stress concentrations under tensile loads  $\Rightarrow$  start cracks
- yielding locally even if under yield strength overall part
- creates zone of distortion and slip bounds along the crystalline boundary
- these coalesce into microscopic cracks
- Cracks will develop more quickly in brittle materials


### Stage II Crack propagation

- crack growth primarily due to tensile loads
- repetitive compressive loads won't cause cracks to grow
- if a corrosive env  $\Rightarrow$  faster propagation
- frequency and mag. of loading plays major role in crack growth rate

## Stage III Fracture

cracks will grow until its size increases past the toughness of material, and at the next cycle  $\Rightarrow$  fracture

### S-N Curve



Ferrous

(A) Low Cycle  $10^0 \leq N \leq 10^3$

$$(S_f)_{10^3} = S_{ec} = f S_{ut} \quad f: \text{Fig 6-18}$$

(C) Infinite Life  $N \geq 10^6$  or  $10^7$

$$S_e' = 0.5 S_{ut} \quad \begin{cases} S_{ut} \leq 200 \text{ ksi} \\ S_{ut} \leq 1400 \text{ MPa} \end{cases} \quad \begin{matrix} \text{Infinite} \\ \text{Life} \end{matrix}$$

$$S_e' = \begin{matrix} 100 \text{ ksi} \\ 700 \text{ MPa} \end{matrix}$$

$$\begin{matrix} S_{ut} > 200 \text{ ksi} \\ S_{ut} > 1400 \text{ MPa} \end{matrix}$$

$$N \geq 10^6 \text{ or } 10^7$$

(2)

(B) High Cycle to Infinite Life  $10^3 \leq N \leq 10^{6\text{ or }7}$

$$S_f = aN^b \quad \text{or} \quad N = \left(\frac{\sigma_{\text{res}}}{a}\right)^{1/b}$$

$$a = \frac{(fS_{\text{ut}})^2}{S_e} \quad b = -\frac{1}{3} \log \left(\frac{fS_{\text{ut}}}{S_e}\right)$$

### Non-ferrous

Use High Cycle (B) for  $N > 10^6$

$N = 5 \times 10^8 \Rightarrow$  Considered infinite life

# Martin Modifying Parameters

$S_e'$ : unmodified endurance limit for a particular material with specimen in fully reversed rotating/bending

$S_e$ : endurance limit at critical location in your machine element under specific conditions

$$S_e = \underbrace{K_a K_b K_c K_d K_e K_f}_{\text{generally } < 1} S_e'$$

## Surface Finish Factor $K_a$

$$K_a = a S_{ut}^b \quad \text{Table 6-2}$$

## Size Factor $K_b$

$$K_b = \begin{cases} 0.87 d_e^{-0.107} & 0.11 \leq d_e \leq 2 \text{ in} \\ 0.91 d_e^{-0.157} & 2 \text{ in} \leq d_e \leq 10 \text{ in} \end{cases}$$

Table 6-3

(4)

Effective diameter, de, Table 6-3

### Load Factor, $K_c$


$$K_c = \begin{cases} 1 & \text{bending} \\ 0.85 & \text{axial} \\ 0.59 & \text{torsion} \end{cases}$$

accounts for shear failure being less than tensile  
 $M_{ss} \Rightarrow S_{ys} = 0.57 S_{yt}$

### Temperature Factor, $K_d$

$$K_d = \frac{S_T}{S_{RT}} = \frac{\text{Tensile strength at operating temp}}{\text{Tensile strength at room temp}}$$

Table 6-4 & also eq 6-26



## Reliability Factor

$$K_e = 1 - 0.08 Z_a$$

Table 6-5  
and A-10

## Misc. Effects Factor

$K_f$

- Residual stress from manufacturing techniques
- Corrosion
- Plating reduces the endurance limit
- Metal Spray " " " "
- stress concentration factors: for fatigue  
are important for both ductile & brittle  
mats.