








Modeling Assumptions For Rack Design




$v/24$





k
stiffness
the end
of center
beam



Crack Growth

Stage I: Crack Initiation

- geometric stress concentrations under tensile loads will start cracks
- yielding locally even if it under the overall yield strength of the part
- creates zones of distortion and slip bands along the crystalline boundaries
- these coalesce into microscopic cracks
- cracks will develop more quickly in brittle materials

Stage II Crack propagation

- crack growth primarily due to tensile loads
- repetitive compressive load will not cause cracks to propagate
- if in corrosive environment \Rightarrow faster propagation
- frequency and amplitude of loading plays important roles in crack growth

Stage III : Fracture

Cracks will grow until its size increases past the toughness of the material, at some next cycle the part fractures

S-N Curve




Fig 6-10 shows data to support this curve

Ferrous

(A) Low Cycle $10^0 \leq N \leq 10^3$

$$S'_{ec} = f S_{ut}$$

$$S_{ut} < 70 \text{ kpsi} \quad f = 0.9$$

$$S_{ut} > 70 \text{ kpsi} \Rightarrow \text{see Fig 6-18}$$

(C) Infinite Life $N \geq 10^6$ and 10^7 cycles

$$S_e' = 0.5 S_{ut} \quad \begin{cases} S_{ut} \leq 200 \text{ kpsi} \\ S_{ut} \leq 1400 \text{ MPa} \end{cases} \quad \text{see Fig 6-17}$$

see Fig 6-17

$$S_e' = 100 \text{ Kpsi} \quad \left\{ \begin{array}{l} S_{ut} \geq 200 \text{ Kpsi} \\ S_{ut} \geq 1400 \text{ MPa} \end{array} \right.$$

$$700 \text{ MPa}$$

Ⓑ High Cycle

$$S_f = a N^b$$

$$N = \left(\frac{\sigma_{rev}}{a} \right)^{1/b}$$

stress fully reversed cycles

$$a = \frac{\overbrace{(f S_{ut})^2}^{S_{ec}'}}{S_e'}$$

$$b = -\frac{1}{3} \log \left(\frac{f S_{ut}}{S_e'} \right)$$

$$S_{ec}' = f S_{ut}$$

How to interpret bus data

FFT: Fast Fourier Transform

Transforms an time signal into frequency domain.



Non-ferrous

Use High Cycle (B) for $N > 10^8$

$N = 5 \times 10^8 \Rightarrow$ typically consider sufficient for an "infinite life" design

Marin Parameters

S_e' : endurance limit of ideal R.R. Moore test specimens for fully reversed

S_e : endurance limit of your non-ideal part under specific conditions

$$S_e = K_a K_b K_c K_d K_e K_f S_e'$$

Surface Finish

$$K_a = a S_{ut}^b$$

Table. 6-2

Size Factor : K_b

equivalent diameter

$$K_b = \begin{cases} 0.87 d_e^{-0.107} & 0.1 \text{ in} \leq d_e \leq 2 \text{ in} \\ 0.91 d_e^{-0.157} & 2 \text{ in} \leq d_e \leq 10 \text{ in} \end{cases}$$

Eq 6-20

Table 6-3 for $d_e \uparrow$

This is only used for bending and torsion!
For axial $K_b = 1$.

Load Factor K_c

$$K_c = \begin{cases} 1 & \text{bending} \\ 0.85 & \text{axial} \\ 0.59 & \text{torsion} \end{cases}$$

If you have combined loads use $K_c = 1$ and use von Mises stress technique in sec 6-14.

Temperature Factor K_d

$$K_d = \frac{S_T}{S_{RT}} = \frac{\text{Tensile strength at actual operating temp}}{\text{Tensile strength at room temperature}}$$




Table 6-14 or eq 6-27

K_e : reliability factor

$$K_e = 1 - 0.08 Z_a$$

Table 16-5
and
A-10

K_f : Misc Effects Factor

You want to lower the endurance limit if:


- residual stress from manufacturing
- Corrosion
- plating: reduces endurance limit
- metal sprag: " " "
- stress concentration factors:
for fatigue these factors are
important for both ductile and brittle.

Process for fatigue analysis


1. Calculate the max stress at critical points in your design.
2. For a given material: S_{ut}, S_e', S_{ec}'
ideal specimen
3. Determine if you have low cycle, high cycle, or infinite. Characterize your dynamic stresses.
4. Calculate actual S_e, S_{ec} ~~to~~ with Marin parameters. (many effects, including stress concentrations)

Example

Given a rotating beam which is simply supported at A & E with $P=6.8 \text{ KN}$ and is going through fully reversed cycles, what is the life of the part if the material is CD 1050 steel?



Bending Moment Diagram



Sum Forces & Moments

$$\sum F = 0 = R_A + R_E - P$$

$$\sum M_A = 0 = (550 \text{ mm}) R_E - (325 \text{ mm}) P$$

$$R_A = 2.782 \text{ KN}$$

$$R_E = 4.018 \text{ KN}$$

reaction forces

The highest bending normal stresses will be at B.

$$M_B = (250 \text{ mm}) R_A \Rightarrow M_B = 695.5 \text{ Nm}$$

1) Calculate nominal max stress.

$$\sigma_{B0} = \frac{M_B c}{I} = \frac{M_B d_1/2}{\frac{\pi d_1^4}{64}} = \frac{32 M_B}{\pi d_1^3} = \frac{32 (695.5 \text{ Nm})}{\pi (0.032 \text{ m})^3}$$

↑
nominal

$\sigma_{B0} = 216.2 \text{ MPa}$

See Figure A-15-9 in appendix.

2) Calculate the specimen endurance limit.

$$S_e' = 0.5 S_{ut} \quad \text{for } S_{ut} < 1400 \text{ MPa}$$

From Table A-20 $S_{ut} = 690 \text{ MPa}$ and $S_y = 580 \text{ MPa}$

$S_e' = 345 \text{ MPa}$

3) Calculate Marin parameters so that the part's endurance limit can be found.

- Surface Finish, K_a

$$K_a = a S_{ut}^b$$

From table 6-2 the cold drawn row gives $a = 4.51$
 $b = -0.265$

$$K_a = (4.51) (690 \text{ MPa})^{-0.265}$$

$K_a = 0.798$

- Size Factor, K_b

We have rotating + bending so $d_e = d_1$

$d_1 < 51 \text{ mm}$ so using eq 6-20

$$K_b = \left(\frac{d_1}{7.62} \right)^{-0.107} = \boxed{0.858}$$

- loading factor, K_c

We have bending so $K_c = 1$

- temperature, K_d

Nothing is said about temperature, so $K_d = 1$.

- reliability, K_e

Nothing said: $K_e = 1$

- misc factors, $K_f = 1$

3) We need to account for the stress concentration due to the fillet.

$$K_f = 1 + q(K_t - 1)$$

From Chart A-75-9 and $r/d = 0.093$
 $D/d = 1.19$ } $K_t = 1.65$

From Fig 6-20

$$q \approx 0.85$$

$$\sigma_B = K_f \sigma_{B0} = (1 + 0.85[1.65 - 1])(216.2 \text{ MPa}) = \boxed{335.7 \text{ MPa}}$$

4) Find S_e

$$S_e = (0.798)(0.858) S_e' = (0.798)(0.858)(345 \text{ MPa})$$

$$\boxed{S_e = 236 \text{ MPa}}$$

$$5) \sigma_B > S_e \quad \text{and} \quad \sigma_B < S_y < S_{ut}$$

$$S_{N=10^3} = S'_{lc} = f S_{ut} = (0.84)(690 \text{ MPa}) = \underline{579.6 \text{ MPa}}$$

f : from Fig 6-18

$$690 \text{ MPa} = 100 \text{ kpsi}, \text{ so } f = 0.84$$

$$\sigma_B < S_{N=10^3}$$

So we have high cycle fatigue!

$$N = \left(\frac{\sigma_B}{a} \right)^{1/b} \quad a = \frac{(f S_{ut})^2}{S_e} \quad b = -\frac{1}{3} \log \left(\frac{f S_{ut}}{S_e} \right)$$

$$a = \frac{[(0.84)(690 \text{ MPa})]^2}{S_e} = 1423 \text{ MPa}$$

$$N = \left(\frac{335.7 \text{ MPa}}{1423 \text{ MPa}} \right)^{1/-0.1308}$$

$$b = -\frac{1}{3} \log \left(\frac{579.6}{236} \right) = -0.1308$$

$$\boxed{N = 68 \times 10^3}$$

The part will fail after this many cycles.