





Non-ferrous



$$S_{ec} = f S_{ut} \quad S_f(5 \times 10^6)$$

$\hookrightarrow f = 0.9$ if $S_{ut} < 70 \text{ Kpsi}$





$f(\text{point A, point B})$

Steps for fatigue design

1. Determine S_e' from test data or

$$S_e' = \begin{cases} 0.5 S_{ut} & \text{if } S_{ut} \leq 200 \text{ kpsi (1400 MPa)} \\ 100 \text{ kpsi (700 MPa)} & \text{if } S_{ut} > 200 \text{ kpsi (1400 MPa)} \end{cases}$$

2. Find S_e using Marin modifying parameters

$$S_e = k_a k_b k_c k_d k_e k_f S_e'$$

Surface Finish

$$k_a = a S_{ut}^b$$

Table 6-2

Size

bending/torsion

$$k_b = \begin{cases} 0.879 d_e^{-0.157} & 0.11 \leq d \leq 2 \text{ in} \\ 0.91 d_e^{-0.157} & 2 \leq d \leq 10 \text{ in} \end{cases}$$

Axial: $k_b = 1$

$d_e \Rightarrow$ effective diameter
(needed for odd shapes
or non-rotating)

Load

$$k_e = \begin{cases} 1 & \text{bending} \\ 0.85 & \text{axial} \\ 0.59 & \text{torsion} \end{cases}$$

Temp

Table 6-4

$K_d = 1$ for room temp

or use

eq

Reliability

K_e

from Table 6-5

Stress Con. Factors

smaller than the static stress con. factors

$$K_f = 1 + q(K_{ts} - 1)$$

$$K_{fs} = 1 + q(K_{ts} - 1)$$

q : notch sensitivity
 \hookrightarrow static stress con. fac

figs 6-20

or 6-21

$$\sigma = K_f \sigma_0$$

or

$$\tau = K_{fs} \tau_0$$

equivalent but use above!

$$k_f = \frac{1}{K_f}$$

Low Cycle Limit (10^3)

$$S_{ec} = f S_{ut}$$

f : from test data or
Fig 6-16

$f = 0.9$ if $S_{ut} < 70 \text{ kpsi}$
L-26-4

High Cycle

$$S_f = a N^b \quad \text{or} \quad N = \left(\frac{\sigma_{rev}}{a} \right)^{1/b}$$

$$\text{where } a = \frac{(f S_{ut})^2}{S_e} \quad b = -\frac{1}{3} \log \left(\frac{f S_{ut}}{S_e} \right)$$

Fluctuating Stress

Find σ_m and σ_a (K_f must be applied to both!)

$$\sigma_m = \frac{(\sigma_{max} + \sigma_{min})}{2} \quad \sigma_a = \frac{|\sigma_{max} - \sigma_{min}|}{2}$$

Apply failure criteria for tension:

modified Goodman

$$\frac{\sigma_a}{S_e} + \frac{\sigma_m}{S_{ut}} = \frac{1}{n} \quad \text{if } \sigma_m > 0$$

or Gerber line

$$\frac{n \sigma_a}{S_e} + \left(\frac{n \sigma_m}{S_{ut}} \right)^2 = 1 \quad \text{if } \sigma_m > 0$$

or compression:

$$\sigma_a = \frac{S_e}{n} \quad \text{if } \sigma_m < 0$$

also check for yielding:

$$\sigma_a + \sigma_m = \frac{S_y}{n}$$

$$\tau_a + \tau_m = 0.5777 \frac{S_y}{n}$$

Note that for torsion:

$$K_c = 0.59, \quad S_{su} = 0.67 S_{ut}, \quad S_{sy} = 0.5777 S_y$$

↑
marin par.

↑
Joeses correction

↑
Distortion energy theory

Finite life


mod. Goodman

$$\sigma_{rev} = \frac{\sigma_a}{1 - (\sigma_m / S_{ut})}$$

Gerber

$$\sigma_{rev} = \frac{\sigma_a}{1 - (\sigma_m / S_{ut})^2}$$

$$N = \left(\frac{\sigma_{rev} / n}{a} \right)^{1/b} \quad \text{F.o.S}$$



σ_{rev} : equivalent fully reversed stress
 for that particular σ_m and σ_a
 in the finite life area